United States Environmental Protection Agency (EPA)
Region 2
290 Broadway
New York, NY 10007-1866

(4)

# Underground Storage Tank (UST) Inspection Form

INSPECTOR NAME(S): Luis Diaz, Bill Hahn DATE: 3/25/13

SIC CODE: 5541 ICIS #: 340003040

## I. Location of Tank(s) ☐ Tribal

Facility Name: US Petroleum #ST 329

Street Address: 2664 Route ~~112~~ 112 (m 5/19/14)

City: Medford State: NY Zip Code: 11763

County: Suffolk

Phone Number: 516-413-9522 Fax Number:

Contact Person(s): ~~516-413-9522~~ James Agsuon

## II. Ownership of Tank(s) ☐ same as location (I.)

Owner Name: US Petroleum

Street Address: —

City: North Bergen State: NJ Zip Code:

County: —

Phone Number: 551-556-8622 Fax Number:

Contact Person(s): Mehmet Bariskan (?)

## IIA. Ownership of Other Facilities

☐Do you own other UST Facilities (Yes) / No

If Yes, How many Facilities MANY How many USTs MANY

## III. Notification

no registration available **

☐ Notification to implementing agency; name Suffolk Co. Dept of Env. Health SVS
State Facility ID # 2-0077

## IV. Financial Responsibility Proof of insurance not available *

☐ State Fund ☐ Private Insurance: Insurer/Policy #
☐ Guarantee ☐ Surety Bond ☐ Letter of Credit
☐ Local Government ☐ Self Insured ☐ **Not Required** (Federal & State government, hazardous substance USTs)

## V. Release History N/A

☐ To your knowledge, are there any public or private Drinking Water Wells in the vicinity ? **Yes / No**

☐ Evidence of release or spills at facility ☐ Greater than ~~25 gallons~~ (estimate)
☐ **Releases reported to implementing agency; if so, date(s)** [280.53]
☐ Release confirmed; when and how
☐ Initial abatement measures and site characterization ☐ Free product removal
☐ Soil or ground water contamination ☐ Corrective action plan submitted
☐ Remediation ongoing ☐ Remediation completed, no further action; date(s)

Notes:

| VI. Tank Information | Tank No. | 1 | 2 | 3 | 4 | 5 | |
|---|---|---|---|---|---|---|---|
| Tank presently in use | | Yes | → | → | → | → | |
| If not, date last used | (see Section XII) | NA | → | → | → | → | |
| If empty, verify 1" or less left | (see Section XII) | NA | → | → | → | → | |
| Capacity of Tank (gal) | | 25,000 | → | → | 10,000 | → | |
| Substance Stored | | G-R | → | Diesel | G-P | Diesel | |
| M/Y Tank installed / Upgraded | | 2/17/11 | → | → | 4/28/94 | → | |
| *Tank Construction:* Bare steel, Sti-P3, Retrofitted sacrificial anode, Impressed Current, Composite, FRP, Interior lining, Vaulted, Double-walled (DW) | | FRP DW | → | → | → | → | |
| Spill Prevention | | Yes | → | → | → | → | |
| Overfill Prevention (specify type) | ① | Yes | → | → | → | → | |
| *Special Configuration:* Compartmentalized, Manifolded | ② | Yes | → | No | → | → | |

## VII. Piping Information

| | | | | | | |
|---|---|---|---|---|---|---|
| *Piping Type:* Pressure, Suction | P | → | → | → | → | |
| *Piping Construction:* Bare steel, Sacrificial Anode, Impressed Current, Flex, FRP, Double-walled (DW) | FRP DW | → | → | → | → | |

**Tank and Piping Notes:** ① ATG with functional external audible/visual alarm used for overfill protection. Tanks also equipped with flapper valve.

② Tank 2 is manifolded with tank 1.

## VIII. Cathodic Protection

N/A ✓

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Integrity Assessment conducted prior to upgrade | | | | | | | |
| *Interior Lining:* | Interior lining inspected | | | | | | |
| *Impressed Current* | CP Test records | | | | | | |
| | Rectifier inspection records | | | | | | |
| *Sacrifical Anode:* | CP test records | | | | | | |

**CP Notes:**



Init/Date 03/25/13

| Tank No. | 1 | 2 | 3 | 4 | 5 | |
|---|---|---|---|---|---|---|
| IX. UST system used solely by Emergency Power Generator | No → | | | | → | |

**X. Release Detection** N/A ☐

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| *Tank RD Methods* | ATG VEEDER ROOT TLS 350 | Yes → | | | | → | (1) |
| | Interstitial Monitoring | | | | | | |
| | Groundwater Monitoring | | | | | | |
| | Vapor Monitoring | | | | | | |
| | Inventory Control w/ TTT | | | | | | |
| | Manual Tank Gauging | | | | | | |
| | Manual Tank Gauging w/ TTT | | | | | | |
| | SIR | | | | | | |
| *12 Months Monitoring Records* (*Must* Make Available Last 12 Months For Compliance) | | Yes → | | | | → | (2) |

**Tank RD Notes:** (State What Months Records Were Available, Describe Any Failures and Describe What Investigation Occurred Due to Failure)

(1) The facility uses the Veeder Root, in combination with sticking the tank, to do a 10-day and 30-day reconciliation.

(2) Release detection records (30-day reconciliation) are available for 12 months

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| *Pressurized Piping RD Methods* | | N/A ☐ | | | | | |
| | Interstitial Monitoring | | | | | | |
| | Groundwater Monitoring | | | | | | |
| | Vapor Monitoring | | | | | | |
| | SIR | | | | | | |
| *12 Months Monitoring Records* | | | | | | | |
| | Annual Line Tightness Test (3) | No → | | | | → | |
| *ALLD* | Present (4) | Unknown → | | | ~~Yes~~ | Yes → | |
| | Annual Test (5) | No → | | | ~~Yes~~ No | ~~No~~ | |

**Piping RD Notes:** (State What Months Records Were Available, Describe Any Failures and Describe What Investigation Occurred Due to Failure)

(3) Records of line tightness testing are not available at facility

(4) The sump covers to Tanks 1-3 could not be removed during the inspection

(5) The leak detectors for Tanks 4 & 5 were tested on 3/6/12. No records of LLD testing for Tanks 1-3

 Init/Date D 3/25/13 11/04/2010

## XI. Repairs

N/A ✓

| | |
|---|---|
| Repaired tanks and piping are tightness tested within 30 days of repair completion | Y □ N □ Unknown □ |
| CP systems are tested/inspected within 6 months of repair of any cathodically protected UST system | Y □ N □ Unknown □ |
| Records of repairs are maintained | Y □ N □ Unknown □ |

## XII. Temporary Closure

N/A ✓

| | |
|---|---|
| CP continues to be maintained | Y □ N □ Unknown □ |
| UST system contains product and release detection is performed | Y □ N □ Unknown □ |
| Cap and secure all lines, pumps, manways | Y □ N □ Unknown □ |

Notes:



Init/Date MD 3/25/13

THE UNITED STATES ENVIRONMENTAL PROTECTION AGENCY (EPA) REGION 2 UST PROGRAM
Ground Water Compliance Section
New York, NY 10007-1866

# Inspector Observation Report

*Inspection of Underground Storage Tanks (USTs)*

□ No violations observed at the conclusion of this inspection.

☑ The above named facility was inspected by a duly authorized representative of EPA Region 2, and the following are the inspector's observations and/or recommended corrective action(s):

Violations Observed:

| Regulatory Citation | Violation Description |
|---|---|
| § 280.22 | Lack of Tank registration ✓ not fed |
| § 280.44(b) | Lack of annual line tightness test records |
| § 280.44(a) | Lack of annual line leak detector test records |
| § 280.41(a) | Lack of approved release detection records |
| § 280.11 | Proof of financial responsibility not available. |
| § | |
| § | |
| § | |

400a

Actions Taken:
□ Field Citation; # _____ ☑ Additional information required ☑ On-site request/Due date 4/in 30 days

Comments/Recommendations:

Name of Owner/Operator Representative:

Duysun Pul
(Please print)

(Signature)

Other Participants: _____

Name of EPA Inspector/representative

Luis Diaz
(Please print)

(Signature)

(Credential Number)

Date of Inspection 3/25/13 Time 9:45 AM/PM



Init/Date LD 3/25/13

## SITE DRAWING

Coord.
N - 40.8209
W - -72.9988

DATE: 3/25/13 TIME ON SITE: 3:30 pm TIME OFF SITE: 4:45 pm

WEATHER: raing

ENVIRONMENTALLY SENSITIVE AREA : Y ☐ N ☑
If "Yes", please describe:

— See following page —

☑ Pictures



Init/Date JD 3/25/13

## Facility Diagram




could not open sump covers. Covers required special tool which was not available on-site.




**LEGEND**

| Symbol | Description | Symbol | Description | Symbol | Description |
|---|---|---|---|---|---|
| ATG | Automatic tank gauge | (D) | Dispenser sensor | GACP | Galvanic anode CP |
| (O) | Fill port-spill bucket/no flapper | (B) | Ball float access port | ICCP | Impressed-current CP |
| (●) | Fill port- spill bucket/flapper | (M) | Mechanical (ALLD) | REC | Rectifier |
| (⊗) | Monitor well – VP/GW | (E) | Electronic (PLLD/ELLD) | [R] | Regular unleaded gasoline |
| (I) | Interstitial Monitor | (V) | Vapor recovery | [P] | Premium/Super unleaded gas |
| (L) | Level sensor | DW | Double-walled | [M] | Mid-grade unleaded gas |
| (T) | Turbine pump | SW | Single-walled | [D] | Diesel |
| ● | Blank/capped port | D | Dispenser | [K] | Kerosene |
| (S) | Sump Sensor | FRP | Fiberglass-reinforced plastic | | |

**Required Fields to be used for ICIS Only**

Compliance Monitoring

Activity: UST Inspection

Inspection Conclusion Data Sheet

1) Did you observe deficiencies (preferred violations) during the on-site inspection?

Deficiencies observed: (Put an **X** for each observed deficiency)

✓ Potential failure to complete or submit a notification, report, certification, or manifest

___ Potential failure to follow or develop a required management practice or procedure

✓ Potential failure to maintain a record or failure to disclose a document

___ Potential failure to maintain/inspect/repair meters, sensors, and recording equipment

___ Potential failure to report regulated events, such as spills, accidents, etc.

2) If you observed deficiencies, did you communicate the deficiencies to the Facility during the inspection? (Yes) / No

3) Did you observe the Facility take any actions during the inspection to address the deficiencies noted? Yes / (No)

If yes, what actions were taken?

4) Did you provide general Compliance Assistance in accordance with the policy on the role of the EPA Inspector In providing Compliance Assistance during Inspections? (Yes) / No

5) Did you provide site-specific Compliance Assistance in accordance with the policy on the role of the EPA Inspector in providing Compliance Assistance during the inspection? (Yes) / No



Init/Date D 3/25/13

# Release Prevention Compliance Measures Matrix

| Regulatory Subject Area | Measure # | SOC Measure / Federal Citation | In Compliance? | | |
|---|---|---|---|---|---|
| | | | N/A | Y | N |
| I. Spill Prevention | 1 | Spill prevention device is present and functional. [280.20(c)(1)(i), 280.21(d)] | | ✓ | |
| II. Overfill Prevention | 2 | Overfill prevention device is present and operational. [280.20(c)(1)(ii), 280.21(d)] | | ✓ | |
| | | ❑ Automatic shutoff is operational (ie., device not tampered with or inoperable ) [280.20(c)(1)(ii)(A), 280.21(d)]<br>❑✓ Alarm is operational. [280.20(c)(1) (ii)(B), 280.21(d)]<br>❑ Alarm is audible or visible to delivery driver. [280.20(c)(1) (ii)(B), 280.21(d)] ❑<br>Ball float is operational. [280.20(c)(1)(ii)(B), 280.21(d)] | [redacted] | | |
| III a. Operation and Maintenance | 3 | Repaired tanks and piping were tightness tested within 30 days of repair completion (not required w/internal inspections or if monthly monitoring is in use). [280.33(d)] | ✓ | | |
| III b. Operation and Maintenance of Corrosion Protection | 4 | CP systems were tested/inspected within 6 months of repair of any cathodically protected UST system. [280.33(e)] | ✓ | | |
| | 5 | Corrosion protection system is properly operated and maintained to provide continuous protection. [280.31(a)(b), 280.70(a)] | ✓ | | |
| | | ❑ UST system (Choose one)<br>❑ UST in operation<br>❑ UST in temporary closure<br>❑ CP System is properly operated and maintained<br>❑ CP system is performing adequately based on results of testing. [280.31(b)]; - or -<br>❑ CP system tested within required period and operator is conducting or has completed appropriate repair in response to test results reflecting CP system not providing adequate protection. | [redacted] | | |

# Release Prevention Compliance Measures Matrix

| Regulatory Subject Area | Measure # | SOC Measure / Federal Citation | In Compliance? | | |
|---|---|---|---|---|---|
| | | | N/A | Y | N |
| III b. Operation and Maintenance of Corrosion Protection (Continued) | 6 | UST systems with impressed current cathodic protection are inspected every 60 days. [280.31(c)] | ✓ | | |
| | 7 | Lined tanks are inspected periodically and lining is in compliance. [280.21(b)(1)(ii)] | ✓ | | |
| IV. Tank and Piping Corrosion Protection | 8 | Buried metal tank and piping (which includes fittings, connections, etc.) is corrosion protected. [280.20(a), 280.20(b), 280.21(b), 280.21(c)] | ✓ | | |
| | | ❑ Buried metal piping components (such as swing joints, flex-connector, etc.) are isolated from the soil or cathodically protected.<br><br>For new USTs - tanks and piping installed after 12/22/88 [280.20(a), 280.20(b)]:<br><br>❑ Steel tank or piping is coated with suitable dielectric material and cathodically protected. [280.20(a)(2), 280.20(b)(2)]<br><br>❑ Tank is fiberglass, clad, or jacketed and piping is fiberglass or flexible plastic. [280.20(a)(1), 280.20(a)(3), 280.20(a)(5), 280.20(b)(1), 280.20(b)(4)]<br><br>❑ Records are available to document that CP is not necessary. [280.20(a)(4)(ii), 280.20(b)(3)(ii)]<br><br>For existing USTs - tanks and piping installed on or before 12/22/88 [280.21(b), 280.21(c)]: ❑<br><br>Tank and piping meet new UST requirements [280.21(a)(1)]<br><br>❑ Steel tank is internally lined. [280.21 (b)]<br><br>❑ Metal tank and piping are cathodically protected. [280.21(b)(2), 280.21(c)] | | | |

Notes: N/A - Indicates that the measure is not applicable.
Any mark in the "N" (No) column means that the facility is not in Significant Operational Compliance (SOC) with Release Prevention Compliance Measures. In order for a compliance measure to be in SOC, all applicable check-box items must be in compliance.

# Release Detection Compliance Measures Matrix

*Instructions - To Determine Compliance Status of Measures #1-7, Work Through the Worksheet "Commonly Used Release Detection Methods" Below.*

| Regulatory Subject Area | Measure # | SOG Measure/ Federal Citation | In Compliance? N/A | Y | N |
|---|---|---|---|---|---|
| I. Release Detection Method Presence and Performance Requirements | 1 | Release detection method is present. [280.40(a)] | | ✓ | |
| | 2 | Release detection system is operating properly (i.e., able to detect a release from any portion of the system that routinely contains product). [(280.40(a)(1)] | | | ✓ |
| | 3 | Release detection system meets the performance standards at 280.43 or 280.44. [(280.40(a)(3)] | | | ✓ |
| | 4 | Implementing agency has been notified of suspected release as required. [(280.40(b)] | ✓ | | |
| | | ❑ Non-passing results reported and resolved in accordance with implementing agency's directions. [280.40(b)] | | | |
| II. Release Detection Testing | 5 | Tanks and piping are monitored monthly for releases and records are available (must have records for the two most recent consecutive months and for 8 months of the last 12 months). [280.41(a), and 280.45(b)] | | | ✓ |
| III. Hazardous Substance UST Systems | 6 | Hazardous substance UST system leak detection meets the requirements (i.e., either secondarily contained or otherwise approved by the implementing agency). [280.42(b)] | ✓ | | |
| IV. Temporary Closure | 7 | Release detection requirements are complied with (i.e., method present, operational, releases investigated and reported as required) for UST systems containing product. [280.70(a)] | ✓ | | |

## Worksheet - Commonly Used Release Detection Methods

| Tank (Choose one) | Pressurized Pipe (Choose Two) | Non-exempt Suction Pipe (Choose one) | Release Detection Method |
|---|---|---|---|
| ❑ | | | **A. Inventory Control with Tank Tightness Testing (T.T.T)**<br>❑ Inventory control is conducted properly.<br>❑ T.T.T. performed as required (See "D" below).<br>❑ Inventory volume measurements for inputs, withdrawals, and remaining amounts are recorded each operating day and reconciled as required. [280.43(a)(1), 280.43(a)(3)]<br>❑ Equipment is capable of 1/8-inch measurement. [280.43(a)(2)]<br>❑ Product dispensing is metered and recorded within local standards for meter calibration to required accuracy. [280.43(a)(5)]<br>❑ Water is monitored at least monthly. [280.43(a)(6)] |

# Release Detection Compliance Measures Matrix

## Worksheet (Continued) - Commonly Used Release Detection Methods

| Tank (Choose one) | Pressurized Pipe (Choose Two) | Non-exempt Suction Pipe (Choose one) | Release Detection Method |
|---|---|---|---|
| ❑ | | | **B. Automatic Tank Gauge (ATG)**<br>❑ ATG is set up properly. [280.40(a)(2)]<br>❑ ATG can detect a 0.2 gal/hr leak rate from any portion of the tank routinely containing product. [280.43(d)(1)] ❑<br>ATG is checking portion of tank that routinely contains product. [280.40(a)(1)] |
| ❑ | | | **C. Manual Tank Gauging (MTG)**<br>❑ Tank size is appropriate for using MTG. [280.43(b)(5)]<br>❑ Tanks 1001 gals (as per EPA memo) and greater restricted to use with T.T.T. (See "D" below) ❑<br>Method is being conducted correctly. [280.43(b)(4)]<br>❑ No liquid was added to or taken out of the tank during the test. [280.43(b)(1)] ❑<br>Equipment is capable of 1/8-inch measurement. [280.43(b)(3)] |
| ❑ | ❑ | ❑ | **D. Tightness Testing** (Safe Suction piping does not require testing)<br>❑ Testing method is capable of detecting a 0.1 gal/hr leak rate from any portion of tank routinely containing product. [280.43(c)]<br>❑ Tightness testing is conducted within specified time frames for method:<br>❑ **Tanks** - every 5 years [280.41(a)(1)]<br>❑ **Pressurized Piping** - annually [280.41(b)(1)(ii)]<br>❑ **Non-exempt suction piping** - every 3 years [280.41(b)(2)]<br>❑ Tightness testing is conducted following manufacturer's instructions. [280.40(a)(3)] |
| ❑ | ❑ | ❑ | **E. Ground Water or Vapor Monitoring**<br>❑ Ground water in the monitoring well is never more than 20 feet from the ground surface. [280.43(f)(2)] ❑<br>Vapor monitoring well is not affected by high ground water. [280.43(e)(3)]<br>❑ Site assessment has been done for vapor or ground water monitoring. [280.43(e)(6), 280.43(f)(7)] ❑<br>Wells are properly designed and positioned. [280.43(e)(6), 280.43(f)(7)] |
| ❑ | ❑ | ❑ | **F. Interstitial Monitoring**<br>❑ Secondary containment can be used to detect a release [280.43(g)(1)], 280.43(g)(2)]<br>❑ Sensor properly positioned. [280.40(a)(2)] |

## Worksheet (Continued) - Commonly Used Release Detection Methods

| Tank (Choose one) | Pressurized Pipe (Choose Two) | Non-exempt Suction Pipe (Choose one) | Release Detection Method |
|---|---|---|---|
| | ☑ | | **G. Automatic Line Leak Detector (ALLD)**<br>☐ ALLD is present and operational. [280.44(a)] No test records available<br>☐ Annual function test of the ALLD has been conducted and records are available. [280.44(a)] |
| ☐ | ☐ | ☐ | **H. Other Methods [e.g., Statistical Inventory Reconciliation (S.I.R.)]**<br>☐ The method can detect a 0.2 gal/hr leak rate or a release of 150 gal within a month and meet the 95/5 requirement [280.43(h)(1)]; or<br>☐ The implementing agency has approved the method as being as effective as tank tightness testing, automatic tank gauging, vapor monitoring, ground water monitoring, or interstitial monitoring and the operator complies with any conditions imposed by agency. [280.43(h)(2)]<br>☐ S.I.R. - Results are received within time frame established by implementing agency. [280.41(a) & 280.43(h)] |

Notes: N/A - Indicates that the measure is not applicable.

**Any mark in the "N" (No) column means that the facility is not in Significant Operational Compliance (SOC) with Release Detection Compliance Measures.**

**In order for a compliance measure to be in SOC, all applicable check-box items must be in compliance.**